

CHEVROLET P1184: SUPERCHARGER INLET PRESSURE (SCIP) SENSOR CIRCUIT HIGH VOLTAGE

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chevrolet P1184 Code Mean?

Condition for setting the DTC: The engine has been running for a calibrated length of time that is determined by the start-up engine coolant temperature (ECT).

Reference Sources

[Chevrolet P1184](#), DTCDECODE.