CHEVROLET P1414: EXHAUST GAS RECIRCULATION (EGR) COOLER BYPASS VALVE CURRENT PERFORMANCE OVERVIEW

Severity : High

DIY Difficulty Level : Intermediate

Repair Cost : \$250-\$650

Can I Still Drive? : Yes (Short-term only)

What Does The Chevrolet P1414 Code Mean?

This code is set when the ECM detects that the EGR cooler bypass valve control circuit current is greater than a calibrated threshold for greater than 2 s.

Conditions for setting the DTC:

- The Ignition is ON.
- The battery voltage is greater than 11 V.
- The EGR cooler bypass valve control circuit is active.
- The starter is not cranking.
- The DTCs run continuously when the above conditions are met.

