CHEVROLET P1655: EVAP PURGE SOLENOID CONTROL CIRCUIT MALFUNCTION OVERVIEW Severity : Medium DIY Difficulty Level : Intermediate Repair Cost : \$100-\$250 Can I Still Drive? : Yes (Short-term only)

What Does The Chevrolet P1655 Code Mean?

Key on or engine running; and the PCM detected an unexpected voltage condition on the EVAP Purge solenoid control circuit for 30 seconds during the CCM test.

What Are The Potential Causes Of The Chevrolet P1655 Code?

- EVAP solenoid control circuit is open, shorted to ground or shorted to power (B+)
- EVAP solenoid power circuit is open (check PCM IGN1 fuse)
- EVAP solenoid is damaged or has failed
- PCM has failed

Reference Sources

GM, 2013, Service Bullettin - Prior To Any Circuit Testing.

