CHEVROLET P1671: CHANGE ENGINE OIL LAMP CONTROL CIRCUIT

OVERVIEW

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$80-\$150

Can I Still Drive? : Yes (Short-term only)

What Does The Chevrolet P1671 Code Mean?

A PCM controlled lamp on at all times most likely indicates that a condition is present which requires the attention of the vehicle operator.

What Are The Potential Causes Of The Chevrolet P1671 Code?

- Poor connection at PCM
- Inspect harness connectors for backed out terminal

Reference Sources

GM, 2013, Service Bullettin - Prior To Any Circuit Testing.

