

CHEVROLET P1BFF: AUXILIARY TRANSMISSION FLUID PUMP MOTOR CONTROL MODULE NOT PROGRAMMED

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$350
Can I Still Drive?	:	No

What Does The Chevrolet P1BFF Code Mean?

The vehicle is ON. The system voltage is 8-18 V.

The control module has detected an internal malfunction, or a control module was not programmed after replacement.

Reference Sources

[Chevrolet Volt Hybrid DTC](#) - OBDG01 HYBRID Diagnostics Document, page 852.