

## CHRYSLER B1002: A/C SWITCH REQUEST INPUT CIRCUIT HIGH

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$200-\$450
Can I Still Drive?	:	Yes

### What Does The Chrysler B1002 Code Mean?

With the ignition on. If the Instrument Cluster (CCN) detects voltage above 4.5 volts for 10 seconds on the (C105) HVAC MUX Control circuit

### What Are The Potential Causes Of The Chrysler B1002 Code?

- (C105) HVAC Mux Control Circuit Shorted To Voltage
- (C105) HVAC Mux Control Circuit Open
- (C955) HVAC Mux Return Circuit Open
- A/C Heater Control
- Instrument Cluster (CCN)

### Reference Sources

[Chrysler B1002](#), DTCDECODE.