

CHRYSLER B1504: LEFT STEERING WHEEL CONTROL SWITCH CIRCUIT

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$345
Can I Still Drive?	:	Yes

What Does The Chrysler B1504 Code Mean?

The Cluster senses that the Left Steering Wheel Control Switch is in the Set position for greater than 20 seconds. Phone related switches have a set time of 600 seconds.

What Are The Potential Causes Of The Chrysler B1504 Code?

Left Steering Wheel Control Switch

Reference Sources

[Chrysler B1504](#), DTCDECODE.