

CHRYSLER B1801: DRIVER (LEFT) DOOR LOCK/UNLOCK SWITCH CIRCUIT LOW

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$350
Can I Still Drive?	:	Yes

What Does The Chrysler B1801 Code Mean?

When the (G161) Driver Door Lock Switch Mux circuit does not switch from low to high for over 30 seconds, this code will set.

What Are The Potential Causes Of The Chrysler B1801 Code?

- (G161) driver door lock switch mux circuit short to ground
- Driver door lock switch
- Totally integrated power module (TIPM)

Reference Sources

[Chrysler B1801](#), DTCDECODE.