CHRYSLER B1A09: RKE FOB 2 PERFORMANCE	
	OVERVIEW
:	Medium
:	Intermediate
:	\$50-\$150
:	Yes
	:

What Does The Chrysler B1A09 Code Mean?

Scrambled messages to the Wireless Ignition Node (WIN) from the FOBIK transmitter.

What Are The Potential Causes Of The Chrysler B1A09 Code?

- Excessive presses from transmitter when out of range
- Fobik transmitter

Reference Sources

Chrysler B1A09, DTCDECODE.