

CHRYSLER B1A31: KEY 8 COMMUNICATION ERROR

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$250
Can I Still Drive?	:	Yes

What Does The Chrysler B1A31 Code Mean?

At ignition on and during Key Programming Mode. When the Wireless Control Module (WCM) does not receive a transponder response after 8 consecutive transponder read attempts within 2.0 seconds

What Are The Potential Causes Of The Chrysler B1A31 Code?

- MULTIPLE KEY OPERATION
- IGNITION KEY
- WIRELESS CONTROL MODULE
- INTERMITTENT WIRING HARNESS PROBLEM

Reference Sources

[Chrysler B1A31](#), DTCDECODE.