

CHRYSLER B1A35: UNIDENTIFIED KEY COMMUNICATION ERROR

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$250
Can I Still Drive?	:	Yes

What Does The Chrysler B1A35 Code Mean?

Whenever a Fob-Integrated-Key (FOBIK) is inserted in the Wireless Ignition Node (WIN) basestation, the WIN performs a self test and resynchronization routine. During the routine, the WIN interrogates the FOBIK, performing various validity and performance tests. The repair of this fault condition relies on whether the FOBIK ID is received by the WIN.

What Are The Potential Causes Of The Chrysler B1A35 Code?

- Fobik
- Wireless ignition node (WIN)

Reference Sources

[Chrysler B1A35](#), DTCDECODE.