

CHRYSLER B1A68: STEERING COLUMN LOCK MODULE BOLT CONTROL LOW

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$900
Can I Still Drive?	:	Yes

What Does The Chrysler B1A68 Code Mean?

This code is set immediately when the Wireless Ignition Node detects the (F892) Ignition Switch Output circuit shorted to ground when the ignition key is removed.

What Are The Potential Causes Of The Chrysler B1A68 Code?

- (F892) IGNITION SWITCH OUTPUT (KEY-IN) CIRCUIT SHORTED TO GROUND
- STEERING COLUMN LOCK MODULE (ELV)
- WIRELESS IGNITION NODE (WIN)

Reference Sources

[Chrysler B1A68](#), DTCDECODE.