

CHRYSLER B222C: VEHICLE CONFIGURATION NOT PROGRAMMED

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$30-\$300
Can I Still Drive?	:	Yes

What Does The Chrysler B222C Code Mean?

Vehicle configuration information not programmed into the Instrument Cluster.

What Are The Potential Causes Of The Chrysler B222C Code?

- NO COMMUNICATION WITH TOTALLY INTEGRATED CONTROL MODULE
- ACTIVE TIPM DTCs
- INSTRUMENT CLUSTER
- TOTALLY INTEGRATED CONTROL MODULE (TIPM)

Reference Sources

[Chrysler B222C](#), DTCDECODE.