CHRYSLER B2254: COLUMN LOCK MODULE INTERNAL	
	OVERVIEW
:	Medium
:	Intermediate
:	\$100-\$900
:	Yes (Short-term only)
	:

What Does The Chrysler B2254 Code Mean?

If the Wireless Ignition Node (WIN) does not receive the correct response message back from the Steering Column Lock Module (ELV).

What Are The Potential Causes Of The Chrysler B2254 Code?

- (A106) fused b+ circuit open
- (F892) ignition switch output (key-in) circuit open
- (Z905) ground circuit open
- (D508) com-lin tire pressure monitor LAN circuit open
- Wireless ignition node (win)
- Steering column lock module (ELV)

Reference Sources

Chrysler B2254, DTCDECODE.

