CHRYSLER B2286: CALIBRATION NOT LEARNED/LOST CALIBRATION OVERVIEW Severity : Medium DIY Difficulty Level : Intermediate Repair Cost : \$40-\$100 Can I Still Drive? : Yes

What Does The Chrysler B2286 Code Mean?

The Headlamp Leveling Module (HIDT) is not calibrated correctly.

What Are The Potential Causes Of The Chrysler B2286 Code?

- HEADLAMP LEVELING MODULE NOT CALIBRATED
- HEADLAMP LEVELNG MODULE (HIDT)

Reference Sources

<u>Chrysler B2286</u>, DTCDECODE.

