

CHRYSLER B2580: DRIVER WINDOW POSITION SENSOR(S) NO SIGNAL

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$70-\$200
Can I Still Drive?	:	Yes

What Does The Chrysler B2580 Code Mean?

The Window Motor Hall Sensor does not generate a signal during a window movement.

What Are The Potential Causes Of The Chrysler B2580 Code?

- Driver window hall sensor circuit faulty wiring
- Driver window motor
- Driver door module (DDM)

Reference Sources

[Chrysler B2580](#), DTCDECODE.