

What Does The Chrysler C1464 Code Mean?

The Drivetrain Control Module (DTCM) detects that the Front Axle Lock Control circuit is shorted low or open.

What Are The Potential Causes Of The Chrysler C1464 Code?

- DRIVETRAIN CONTROL RELAY
- DRIVETRAIN CONTROL RELAY CONTROL CIRCUIT OPEN OR HIGH RESISTANCE
- FRONT AXLE LOCK CONTROL CIRCUIT SHORTED TO GROUND
- FRONT AXLE LOCK CONTROL CIRCUIT OPEN OR HIGH RESISTANCE
- DRIVETRAIN CONTROL MODULE (DTCM)

Reference Sources

Chrysler C1464, DTCDECODE.

