

What Does The Chrysler C147C Code Mean?

The Drivetrain Control Module (DTCM) detects that the Front Axle Lock Control circuit is shorted low.

What Are The Potential Causes Of The Chrysler C147C Code?

- Drivetrain control relay
- Drivetrain control relay control circuit open or high resistance
- Drivetrain control relay control circuit shorted to ground
- Drivetrain control module (DTCM)

Reference Sources

Chrysler C147C, DTCDECODE.

