

CHRYSLER C1597: TPM SYSTEM DEACTIVATED-WINTER MODE

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$100
Can I Still Drive?	:	No

What Does The Chrysler C1597 Code Mean?

When this DTC is active the TPM Module will enter a deactivation mode (Winter Mode) and the TPM system becomes deactivated. If winter tires and wheel assemblies are installed, no repair is required.

What Are The Potential Causes Of The Chrysler C1597 Code?

- Non-FCC compliant components
- Tire pressure monitoring (TPM) sensors not present
- Tire pressure monitoring (TPM) sensors
- Tire pressure monitoring (TPM) module

Reference Sources

[Chrysler C1597](#), DTCDECODE.