LOW			
		LOW	
		OVERVIEW	
Severity	:		High
Severity	•		111811
DIY Difficulty Level	:		Advanced
Repair Cost	:	\$100-\$350	

What Does The Chrysler P127C Code Mean?

Battery voltage greater than 10.4 volts and the ASD sense switch is on. Totally Integrated Power Module (TIPM) requesting Fuel Pump operation. Actual Fuel Pump state is not equal to desired state. One Trip Fault. Three good trips to turn off the MIL

What Are The Potential Causes Of The Chrysler P127C Code?

- (N1) fuel pump control output circuit shorted to ground
- Fuel pump
- Totally integrated power module (TIPM)

Reference Sources

Chrysler P127C, DTCDECODE.

