

CHRYSLER P1404: EGR POSITION SENSOR RATIONALITY CLOSED

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$450
Can I Still Drive?	:	Yes

What Does The Chrysler P1404 Code Mean?

When Monitored: Engine running. Set Condition: The EGR flow or valve movement is not what is expected. Two Trip Fault.

What Are The Potential Causes Of The Chrysler P1404 Code?

- Good trip equal to zero
- EGR solenoid assembly
- EGR position sensor signal circuit shorted to ground
- EGR solenoid control circuit short to ground
- EGR position internal failure
- PCM

Reference Sources

[Chrysler P1404](#), DTCDECODE.