

CHRYSLER P1524: OIL PRESSURE OUT OF RANGE - CAMSHAFT ADVANCE/RETARD DISABLED

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$80-\$200
Can I Still Drive?	:	No

What Does The Chrysler P1524 Code Mean?

The engine oil pressure never reaches the calibrated specification to allow the Variable Valve Timing (VVT) activation.

What Are The Potential Causes Of The Chrysler P1524 Code?

- Engine oil level low
- Engine oil aerated or contaminated
- Incorrect engine oil filter
- Insufficient oil pressure due to a mechanical failure in the oiling system
- Engine oil pressure sensor
- Powertrain control module (PCM)

Reference Sources

[Chrysler P1524](#), DTCDECODE.