

CHRYSLER P1594: CHARGING SYSTEM VOLTAGE TOO HIGH

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$375-\$1100
Can I Still Drive?	:	Yes

What Does The Chrysler P1594 Code Mean?

Engine started, and the PCM detected the Charging System voltage was too high even after it tried to lower the output.

Note: The Generator illuminates when this code sets

What Are The Potential Causes Of The Chrysler P1594 Code?

- Battery temperature Sensor is damaged or has failed (skewed)
- Generator field driver circuit is shorted to ground
- Generator has an internal short circuit condition
- PCM has failed

Reference Sources

[Chrysler P1594](#), DTCDECODE.