

## CHRYSLER P1DD1: INPUT-TURBINE SPEED SENSOR 1 GRADIENT FAULT

### OVERVIEW

Severity	:	<div style="background-color: red; color: white; padding: 2px 10px;">High</div>
DIY Difficulty Level	:	<div style="background-color: #e69d00; color: white; padding: 2px 10px;">Intermediate</div>
Repair Cost	:	\$200-\$290
Can I Still Drive?	:	No

### What Does The Chrysler P1DD1 Code Mean?

The Transmission Control Module (TCM) can detect rationality failures of the input (turbine) speed sensor and output speed sensor signals as well as the wheel speed and engine speed signals received through the Controller Area Network (CAN).

### What Are The Potential Causes Of The Chrysler P1DD1 Code?

- P4 annulus drum
- Transmission control module (TCM)

### Reference Sources

[Chrysler P1DD1](#), DTCDECODE.