CHRYSLER U1	113: LC	OST A/C PRESSUI	RE MESSAGE
		OVERVIEW	
Severity	:	M	edium
DIY Difficulty Level	:		Advanced
Repair Cost	:	\$500-\$1000	
Can I Still Drive?	:	Yes	

What Does The Chrysler U1113 Code Mean?

The Powertrain Control Module (PCM) doesn't receive the A/C Pressure signal over the CAN C bus from the TIPM.

What Are The Potential Causes Of The Chrysler U1113 Code?

- Can C bus circuit open or shorted
- Totally integrated power module (TIPM)
- Powertrain control module (PCM)

Reference Sources

Chrysler U1113, DTCDECODE.

