

CHRYSLER U113E: LOST COMMUNICATION WITH INTELLIGENT BATTERY SENSOR

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Chrysler U113E Code Mean?

The Body Control Module (BCM) does not receive LIN Bus messages from the Intelligent Battery Sensor (IBS) for greater than 180 milliseconds.

What Are The Potential Causes Of The Chrysler U113E Code?

- FUSED B(+) CIRCUIT OPEN OR SHORTED TO GROUND (OPEN FUSE)
- GROUND CIRCUIT OPEN
- LIN BUS CIRCUIT OPEN
- INTELLIGENT BATTERY SENSOR (IBS)

Reference Sources

[Chrysler U113E](#), DTCDECODE.