

CHRYSLER U140E: IMPLAUSIBLE VEHICLE CONFIGURATION DATA RECEIVED

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$450-\$1200
Can I Still Drive?	:	No

What Does The Chrysler U140E Code Mean?

The Totally Integrated Power Module (TIPM) Indicates that the Vehicle Configuration data has not been programmed.

What Are The Potential Causes Of The Chrysler U140E Code?

- Totally integrated power module (TIPM) not configured
- Anti-lock brake system (ABS) module

Reference Sources

[Chrysler U140E](#), DTCDECODE.