

DODGE B10EE: CONDENSER FAN CONTROL CIRCUIT OVERCURRENT

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$450-\$900
Can I Still Drive?	:	Yes

What Does The Dodge B10EE Code Mean?

With the ignition on. The Totally Integrated Power Module (TIPM) will set this DTC if it detects an overcurrent condition on the (N112) High Speed Radiator Fan Control circuit for more than 500 ms when Radiator Fan operation is requested

What Are The Potential Causes Of The Dodge B10EE Code?

- BLOCKAGE STALLING RADIATOR FAN
- RADIATOR FAN
- TIPM

Reference Sources

[Dodge B10EE](#), DTCDECODE.