

DODGE B1804: DRIVER DOOR LOCK/UNLOCK SWITCH INPUT STUCK UNLOCK

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$350
Can I Still Drive?	:	Yes

What Does The Dodge B1804 Code Mean?

At all times when battery power is supplied to the Instrument Cluster. When the Instrument Cluster senses voltage to the driver door lock switch between 0.5 and 1.5 volts for over 10 seconds, this code will set.

What Are The Potential Causes Of The Dodge B1804 Code?

- (G161) driver door lock switch mux circuit partial short to ground
- Driver door lock switch stuck
- Instrument cluster

Reference Sources

[Dodge B1804](#), DTCDECODE.