
DODGE P1005: MANIFOLD TUNING VALVE CONTROL PERFORMANCE		
		OVERVIEW
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$150-\$300
Can I Still Drive?	:	Yes

What Does The Dodge P1005 Code Mean?

The Powertrain Control Module (PCM) compares the circuit feedback to a calibrated closed range when the circuit is de-energized or to a calibrated open range when the circuit is energized. If the value is determined to be out of the calibrated range in either the de-energized or energized state for more than a calibrated amount of time, this DTC will set.





P1005 Dodge wiring diagram



What Are The Potential Causes Of The Dodge P1005 Code?

- MTV control circuit shorted to voltage
- MTV control circuit shorted to ground
- MTV control circuit open or high resistance
- Ground circuit open or high resistance
- manifold tune valve assembly
- Powertrain Control Module (PCM)

Reference Sources

Dodge P1005, DTCDECODE.

