

DODGE P1111: ELECTRONIC THROTTLE CONTROL - UNABLE TO CLOSE - BANK 2

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$350-\$500
Can I Still Drive?	:	No

What Does The Dodge P1111 Code Mean?

During an End-of-Line throttle learn, service ETC Relearn and Spring test. When the PCM detects a failure of throttle body 2's plate to return to within a calibratable tolerance of its default position. Fault set when the throttle plate's actual default position is greater than the expected default position. One trip fault. Three good trips to turn off the MIL

What Are The Potential Causes Of The Dodge P1111 Code?

- OBSTRUCTION IN THE THROTTLE BORE
- THROTTLE PLATE JAMMED AGAINST THE BORE
- ETC MOTOR/THROTTLE BODY

Reference Sources

[Dodge P1111](#), DTCDECODE.