

DODGE P1622: O2 SENSOR REFERENCE VOLTAGE CIRCUIT HIGH

OVERVIEW

Severity	:	<div>High</div>
DIY Difficulty Level	:	<div>Intermediate</div>
Repair Cost	:	\$150-\$500
Can I Still Drive?	:	Yes (Short-term only)

What Does The Dodge P1622 Code Mean?

The O2 Sensor Reference Signal voltage is above 3.7 volts for 9.0 seconds.

What Are The Potential Causes Of The Dodge P1622 Code?

- O2 sensor return circuit shorted to voltage
- O2 sensor return circuit open/high resistance
- Oxygen (O2) sensor
- Powertrain control module (PCM)

Reference Sources

[Dodge P1622](#), DTCDECODE.