FIAT P1523: VVA LOW OIL PRESSURE		
		OVERVIEW
Severity	:	Medium
DIY Difficulty Level	:	Beginner
Repair Cost	:	\$100-\$150
Can I Still Drive?	:	Yes

## What Does The FIAT P1523 Code Mean?

The PCM detects Less than twelve intake manifold pulsations while the engine is cranking.

## What Are The Potential Causes Of The FIAT P1523 Code?

- Engine oil level low
- Engine oil incorrect
- Engine oil contaminated
- Engine oil pressure insufficient or excessively high to the multi air actuators
- Broken timing belt / bent or broken valves
- Powertrain control module (PCM)

## **Reference Sources**

FIAT P1523, DTCDECODE.

