

FORD B103C: THERMOELECTRIC DRIVER OPEN LOAD

OVERVIEW

Severity	:	Low
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$70-\$350
Can I Still Drive?	:	Yes (Short-term only)

What Does The Ford B103C Code Mean?

If SCME outputs to the driver seat backrest or cushion blower motor are open, disconnected or a blower motor resistance greater than 90,000 ohms is sensed, the SCME continues normal operation and sets this DTC .

Reference Sources

[Technical Service Bulletins - 2015 Ford Mustang V6-3.7L](#), B103C, page 1.