

FORD B1113: PASSENGER THERMAL ELECTRIC DEVICE CONTROL OVERTEMPERATURE FAULT

OVERVIEW

Severity	:	Low
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$70-\$350
Can I Still Drive?	:	Yes (Short-term only)

What Does The Ford B1113 Code Mean?

If the SCME blower motor driver integrated circuit temperature exceeds 175° C (347° F), the SCME shuts down the driver seat system and sets this DTC .

Reference Sources

[Technical Service Bulletins - 2015 Ford Mustang V6-3.7L](#), B1113, page 2.