| FORD P1513: INTAKE MANIFOLD RUNNER CONTROL MALFUNCTION (BANK 1) | | |
|---|---|--------------|
| | | OVERVIEW |
| Severity | : | Medium |
| DIY Difficulty Level | : | Advanced |
| Repair Cost | : | \$100-\$1800 |
| Can I Still Drive? | : | Yes |

What Does The Ford P1513 Code Mean?

Engine started, and the PCM detected the IMRC Monitor indicated the IMRC was not functioning correctly during the self-test period.

What Are The Potential Causes Of The Ford P1513 Code?

- IMRC actuator cable/gears are seized, or the cables are improperly routed or seized
- IMRC control circuit open, shorted or the VPWR circuit is open
- IMRC housing return springs are damaged or disconnected
- Leaky vacuum reservoir, vacuum lines loose or dam

Reference Sources

<u>2007 Powertrain Control Emissions Diagnosis On Board Diagnosis</u> - Sections 4: Powertrain DTC Charts and Descriptions, P1513, page 113.

