



FORD U101E: INVALID INTERNAL CONTROL MODULE MONITORING DATA RECEIVED FROM GEAR SHIFT MODULE

OVERVIEW

Severity	:	 Medium
DIY Difficulty Level	:	 Advanced
Repair Cost	:	\$200-\$900
Can I Still Drive?	:	Yes

Reference Sources

[ProDemand Automotive Repair Information for U101E](#) - 2015 Lincoln MKC Base 2.3L, page 4.