HONDA B1079: DAYTIME RUNNING LIGHTS MALFUNCTION OVERVIEW Severity : Medium DIY Difficulty Level : Intermediate Repair Cost : \$100-\$300 Can I Still Drive? : Yes (Short-term only)

What Does The Honda B1079 Code Mean?

This code indicates headlight high beam malfunction, one or both.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Honda B1079 Code?

- Faulty fuse and/or bulb
- Loose or poor connections
- Poor ground
- "Open" or "Short"
- Faulty daytime running light control unit
- Faulty relay control module

Reference Sources

Honda B1079, DTCDECODE.

