

HONDA B1178: F-CAN COMMUNICATION LINE ERROR

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Advanced</div></div>
Repair Cost	:	\$80-\$400
Can I Still Drive?	:	Yes (Short-term only)

What Does The Honda B1178 Code Mean?

Poor communication on the (F-Can) Fast controller Area Network line.

What Are The Potential Causes Of The Honda B1178 Code?

- Check for Fuel and Emissions Systems DTCs first, then retest
- Loose or poor connection between the Gauge Control Module and the PCM
- "Open" or "Short" between Gauge Control Module and the PCM
- Update the PCM if it does not have the latest software
- Faulty Gauge Control Module
- Faulty PCM

Reference Sources

[Body Electrical Repair Information for B1178](#) - American Honda Motor, page 265.