

What Does The Hyundai B1477 Code Mean?

The SRSCM sets DTC B1477 if the measured resistance value of PCAB circuit is more than the threshold value.

*In this case, SRSCM checks if there's any fault in circuit by sending current for a while.

What Are The Potential Causes Of The Hyundai B1477 Code?

- Poor connection of connected part.
- Poor connection between shorting bar and release pin.
- Faulty CAB.
- Faulty SRSCM.

Reference Sources

SRSCM (SRS Control Module) General Information for B1477 - Hyundai Genesis Coupe, pages 217-219.

