

HYUNDAI C1235: PRIMARY PRESSURE SENSOR-ELECTRICAL

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$70-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Hyundai C1235 Code Mean?

Pressure sensor voltage is is not within normal range.

What Are The Potential Causes Of The Hyundai C1235 Code?

- Open or short of pressure sensor circuit
- Faulty pressure sensor
- Faulty HECU

Reference Sources

[Brake System Repair Information for C1235](#) - Page 71.