HYUNDAI C1235: PRIMARY PRESSURE SENSOR-ELECTRICAL OVERVIEW Severity : Medium DIY Difficulty Level : Intermediate Repair Cost : \$70-\$300

Yes (Short-term only)

What Does The Hyundai C1235 Code Mean?

Pressure sensor voltage is is not within normal range.

What Are The Potential Causes Of The Hyundai C1235 Code?

- Open or short of pressure sensor circuit
- Faulty pressure sensor

Can I Still Drive?

• Faulty HECU

Reference Sources

Brake System Repair Information for C1235 - Page 71.

