

INFINITI C1803: EXHAUST SOLENOID

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$200-\$500
Can I Still Drive?	:	Yes (Short-term only)

What Does The Infiniti C1803 Code Mean?

- Driving transistor for the exhaust valve solenoid is OFF and monitor voltage continues at a high level for more than 10 seconds.
- Driving transistor for the exhaust valve solenoid is ON and monitor voltage continues at a low level for more than 5 seconds.

What Are The Potential Causes Of The Infiniti C1803 Code?

Open or short circuit in the exhaust valve solenoid control circuit.

Reference Sources

[Suspension Control System Repair Information for C1803](#) - 2008 QX56, page 11.