

INFINITI P1444: CANISTER PURGE VOLUME CONTROL VALVE CIRCUIT MALFUNCTION:

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$130-\$750
Can I Still Drive?	:	Yes (Short-term only)

What Does The Infiniti P1444 Code Mean?

Engine started, vehicle driven at cruise speed at light engine load, and the PCM detected purge flow through the canister with the Purge Volume Control valve commanded closed during the test.

What Are The Potential Causes Of The Infiniti P1444 Code?

- EVAP control system pressure sensor is damaged or has failed
- EVAP purge volume control valve is stuck open
- EVAP canister vent control valve is damaged or has failed
- EVAP canister is damaged, or hoses are connected incorrectly

Reference Sources

[Infiniti P1444](#), DTCDECODE.