

INFINITI U1206: GPS RAM

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$250-\$1000
Can I Still Drive?	:	Yes (Short-term only)

What Does The Infiniti U1206 Code Mean?

Internal malfunction of AV control unit (GPS malfunction) is detected. An intermittent error caused by strong radio interference may be detected unless any symptom (GPS reception error, etc.) occurs.

How Can You Fix The Infiniti U1206 Code?

Replace the AV control unit if the malfunction occurs constantly.

Reference Sources

[Infiniti M35/M45 Y50 Service Repair Manual](#) - 2007, page AV-105