

## INFINITI U1207: GPS RTC

### OVERVIEW

|                      |   |                       |
|----------------------|---|-----------------------|
| Severity             | : | High                  |
| DIY Difficulty Level | : | Advanced              |
| Repair Cost          | : | \$250-\$1000          |
| Can I Still Drive?   | : | Yes (Short-term only) |

### What Does The Infiniti U1207 Code Mean?

An internal malfunction is detected in AV control unit (GPS malfunction). An intermittent error caused by strong radio interference may be detected unless any symptom (GPS reception error, etc. ) occurs.

### What Are The Potential Causes Of The Infiniti U1207 Code?

Replace AV control unit.

### Reference Sources

[Infiniti M35/M45 Y50 Service Repair Manual](#) - 2007, page AV-105