

JEEP B154F: LOST CRANKSHAFT PULSE SIGNAL

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Jeep B154F Code Mean?

The Amplifier (AMP) does not detect the engine crankshaft pulse signal from the PCM.

What Are The Potential Causes Of The Jeep B154F Code?

- Crankshaft pulse signal circuit shorted to voltage
- Crankshaft pulse signal circuit open
- Crankshaft pulse signal circuit shorted to ground
- PCM
- Amplifier

Reference Sources

[Jeep B154F](#), DTCDECODE.