

JEEP U1106: CAN C MUTE - SIGNAL MISSING

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Jeep U1106 Code Mean?

This diagnostic checks the status of the CAN communication between TCM and its connected CAN nodes. When the TCM CAN network is not in "BUS OFF" status but TCM does not receive acknowledgement flags from the other nodes after its CAN transmissions, a "CAN MUTE" failure is detected.

What Are The Potential Causes Of The Jeep U1106 Code?

- (D65) can c bus (+)circuit shorted to ground
- (d64) can c bus (-)circuit shorted to ground
- (d65) can c bus (+)circuit shorted to voltage
- (d64) can c bus (-)circuit shorted to voltage
- (d65) can c bus (+)circuit shorted to (d64) can c bus (-) circuit
- Antilock brake module
- Powertrain control module (PCM)
- Transmission control module (TCM)
- All wheel drive control(AWD) module
- Steering angle sensor(SAS)
- Totally integrated power module (TIPM)

Reference Sources

[Jeep U1106](#), DTCDECODE.