

KIA P1410: EVAP PURGE SOLENOID CIRCUIT HIGH INPUT

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$250
Can I Still Drive?	:	Yes (Short-term only)

What Does The Kia P1410 Code Mean?

Engine running and the PCM detected the EVAP Purge solenoid control signal was in a continuous high state during the CCM test.

What Are The Potential Causes Of The Kia P1410 Code?

- EVAP purge solenoid control circuit shorted to system power
- EVAP purge solenoid is damaged or has failed
- PCM is damaged

Reference Sources

[Kia P1410](#), DTCDECODE.