Lexus P1277: Port Injector Circuit No. 2

OVERVIEW
Severity
:
High
DIY Difficulty Level
:
Intermediate
Repair Cost
:
\$350-\$850
Can I Still Drive?

What Are The Potential Causes Of The Lexus P1277 Code?

- Open or short in injector for port injection circuit
- IG2 fuse

No

• Injector for port injection

Reference Sources

Lexus P1277, DTCDECODE.

